

General Environmental Incident Summary

Incident: 3603 **Date/Time Notice:** 1/11/2015 10 **DEM Incident No:**
Responsible Party: Atlast Energy Services
Date Incident: 1/11/2015 **Time Incident:** 0010 **Duration:** 90 days
County: Williams **Twp:** 156 **Rng:** 101 **Sec:** 33 **Qtr:** NE NW SE
Lat: 48.25637 **Long:** -103.49920 **Method:** Interpolation from map
Location Description: 6 miles North 2mile west of Williston ND

Submitted By: Levern Stiller **Affiliation:** Lessee
Address: Box 75
City: Clearbrook **State:** MN **Zip:** 56634

Received By:

Contact Person: Jason Brinkerhoff
1021Sage Circle
Heber City, UT 84032

Distance Nearest Occupied Building: 1000 Feet **Release Contained:** Yes

Type of Incident: Oil Barrel

Description of Released Contaminant: Waste oil

Volume Spilled: 30.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Yes

Cause of Incident:

Holes shot in oil barrel

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

May leak in to surface water

Action Taken or Planned:

None will remove soil and barrel

Wastes Disposal Location: Wesco Gibson disposal west of Williston ND

Agencies Involved:

Updates

Date: 1/11/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release due to vandalism. Release of used oil to the ground surface, possibly near a water body. Followup is necessary to confirm adequate cleanup.

Date: 2/19/2015 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

15:00 The weather was partly cloudy and 32 °F with wind from the west at 10 mph. The site is a big lot with a small trailer in the southwest corner. Talked to the lessee. The barrel was in the northwest corner of property. The property is owned by the Utah contact. There are a couple of five gallon pails containing oil and water in this area. On the north side of the property there is a drainage that drains the property from the west. In this area is another empty barrel, but I did not see any oil staining around this barrel or anything else in the drainage. The barrel is currently frozen down; the contact did not know where it came from, but he will remove it. The reported barrel had been hauled away to disposal along with impacted soil. Could not see pad area due to fresh layer of snow. The lessee will contact the NDDoH when the pails and barrel are removed. Further followup needed. 48 17.479, -103 40.431

Date: 3/12/2015 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

I arrived at the site at 15:57 p.m. The weather is clear, 61°F, with the wind from the northwest at 10-15 mph. The barrel and the oil pails have been removed. No further followup needed at this time.